

To Clear the SEPRELD folder under RDS:

This should be done frequently if you are switching between different diagnostics discs quite often. This document is the "back door" (Windows Explorer) way of clearing SEPRELD. It can also be done with the T4/WDS utility CD, however that method does not show you how many files you have that need to be cleared. By going in the "back door" (Windows Explorer), you can actually see that if the count of files before hitting the delete button is 250 or higher, clearing the SEPRELD folder's files will improve laptop performance.

From the T4 Welcome Screen:

Press (Ctrl + Alt) + X to get to the 'Windows Explorer' screen.

Click on the plus (+) next to 'My Computer' on the left side.

Click on the plus (+) next to 'Local Disk C'.

This opens up a list of files under 'Local disk C'.

Look for the folder titled 'RDS' and click on the plus (+) next to 'RDS'.

Look under 'RDS' for the last folder titled SEPRELD and left click once on the name SEPRELD to highlight it.

This shows a list of the files on the right that are in the SEPRELD folder.

Hit 'Ctrl + A' on the keyboard to select all of the files shown.

Hit 'Delete' on the keyboard and answer YES to the message window that pops up to confirm deletion of the files.

(Clearing the SEPRELD folder's files will improve performance, especially if the count of files before hitting the delete button is 250 or higher.)

Click on the red 'X' in the very top right of the screen to return to the 'Welcome to T4 Main Menu'.

If you have any questions during this process, please contact the T4 Tech Support Line at (866) 578-4872.